Headphones

Use instructions below or refer to the detector manual. Manuals are also available at www.minelab.com

Connecting Headphones

Always use headphones with a ¼" jack.

1. Open the rubber headphone cover located on the left hand side of the control box.
2. Plug the headphone jack into the socket.
3. When the detector is turned on, the headphones icon will appear on the LCD to indicate that the headphones are connected.

> *When not using headphones, keep the rubber cover closed to protect the control box electronics from moisture and dust.*