SAFETY RECALL NOTICE

TROY-BILT TB30 RIDING LAWN MOWERS

Store SKU	SKU Description	Internet #	UPC#	THD S/O SKU	Model Number
1005211881	RECON TROYBILT 30IN REAR RIDER				
1006771776	TROY-BILT 30" 10.5HP BRIGGS RER	317834458	043033596867		13AC26JD023
1004822873	TROYBILT 30IN REAR RIDER 382CC	314854371	043033593804		13B726JD023
1004822873	TROYBILT 30IN REAR RIDER 382CC	311264929	043033590926	100470423	8 13A726JD023









Products Affected: Only the model numbers shown above, and within the serial number range, 1G20MB20001 through 1L17MB20228 (manufactured between July 20, 2021, and December 17, 2021), as indicated on your model plate located under the seat, are included in the recall. The second through fifth characters of the serial number identify the manufacturing date. The second character is the month. Months are listed A (January) though L (December). The third and fourth characters are the day of the month. The fifth character is a letter representing the year of manufacture. In this case its letter M for 2021. Also, products with a green "X" on the model plate or products which fall outside the affected serial number range are not affected and are OK to continue using. **Affected products were sold between July 20, 2021, and January 24, 2022.**

Hazard: Riding mower may continue to drive at a speed of about (1) mph when clutch/brake pedal is fully depressed posing a potential for a low-speed loss of control or crash.

What Consumers Should Do: Consumers should stop using the riding mower and call 1-888-848-6038 for information to obtain service for a replacement drive belt free of charge.

DO NOT USE AN AFFECTED PRODUCT

If you need assistance locating or reading the model or serial number of your product, or have any other questions, please call our Recall Hotline toll-free at 1-888-848-6038 between 8:30 AM and 5:00 PM EST

Monday through Friday
Or visit our websites
http://www.mtdproducts.com or
www.troybilt.com or
www.homedepot.com