Recall Information

Frigidaire Stainless-Steel 30-inch 4 Burner and 36-inch 5 Burner Gas Cooktops

Recall Date: 8/31/2023





| Store SKU # | Product Description | UPC | Model # | Internet # | Online SKU # |
|--------------|---|--------------|------------|------------|--------------|
| 1 1001831929 | 36 in. Gas Cooktop in Stainless Steel with 5 Burners | 057112992105 | FFGC3626SS | 207083726 | 1001831929 |
| I 1004679983 | 30 in. Gas Cooktop in Stainless Steel with 4 Burners | 057112992075 | FFGC3026SS | 207083723 | 1001831922 |

Name of Product: Frigidaire Stainless-Steel 30-inch 4 Burner and 36-inch 5 Burner Gas Cooktops

Hazard: Plastic control knobs with a black shaft on the cooktop can crack or break during use, posing a risk of gas leak, fire hazard.

Remedy: Consumers should immediately stop using the recalled cooktops, check for plastic control knobs with a black shaft and contact Electrolux Group for a free set of replacement knobs. Consumers can continue to use knobs with a chrome-colored shaft. The firm is contacting known purchasers directly.

Consumer Contact: Online at www.Cooktopknobrecall.com or online at www.Frigidaire.com and click "Recall Information" under the "Owner Support" tab at the top of the homepage or under Customer Service at the bottom of the homepage for more information or by phone at 800-314-3998 Monday through Friday from 8:30 a.m. to 8 p.m. ET or via email at cooktopknobrecall@electrolux.com.