

# Important Safety Notice

Emerson Tool Company Announces Voluntary Corrective Action for 6 and 9 Gallon NXT wet/dry vacuums

**Hazard:** The on/off switch can be pulled out in a way that could expose a user to an energized wiring connector, creating a potential shock hazard.

## What to do:


Check to see if you have an affected unit and go online at [www.emerson.com/en-us/commercial-residential/emerson-tool-company](http://www.emerson.com/en-us/commercial-residential/emerson-tool-company) to order a replacement Powerhead Assembly.

Or, contact Emerson Tool Company toll-free at 1-888-847-8718 between 8 a.m. and 5 p.m. CT Monday through Friday.


## Models Affected

**RIDGID®  
HD06000**

Packaging




Front




Model Number  
Location on Back

Model: HD06000




**RIDGID®  
HD09000**

Packaging




Front



Model Number  
Location on Back

Model: HD09000



SKU #	Description	UPC	Model #	Internet #
222868	6 Gal. 3.5-Peak HP NXT Wet/Dry Vac	648846022895	HD0600	304005957
223340	9 Gal. 4.25-Peak HP NXT Wet/Dry Vac	648846022901	HD0900	304005985