

Recall Information

Williams Fire Extinguishers and Suppressors

Recall Date: December 6, 2019

SKU #	Product Description	UPC	Model #	Internet #
1004092460	Cooktop Fire Suppressor	655002278997	675-3D	207122403 204656708



Name of Product: Williams Cooktop Fire Suppressors

Hazard: The StoveTop FireStop (STFS) Rangehood and Microhood Automatic Cooktop Fire Suppressors can fail to activate the sealed openings that allow the suppressant powder to feed out of the canister and suppress the fire.

Remedy: Consumers should immediately stop using the recalled fire suppressors and contact WilliamsRDM to receive free replacements.

Consumer Contact: WilliamsRDM StoveTop FireStop toll-free at 888-616-7976 from 8 a.m. to 5 p.m. CT Monday through Friday, email at stfs@stovetopfirestop.com, or online at www.stovetopfirestop.com and click on "Recall 2018" at the bottom of the page, or visit <https://stovetopfirestop.com/recall2018/> for more information.

Post until April 6, 2020